


PCN Number:	20130423000	PCN Date:	05/01/2013
Title:	DM814x, DM812X, DRA64X, AM387x, DM814xSEC Data Sheet		
Customer Contact:	PCN Manager	Phone:	+1(214) 480-6037
Dept:	Quality Services		
Change Type:	<input checked="" type="checkbox"/> Electrical Specification		
PCN Details			
Description of Change:			
<p>The product datasheet(s) is being updated to change to device power-up/down supply sequenceing.</p> <p>The following change history provides further details. These changes may be reviewed at the datasheet links provided.</p> <p>TMS320DM814x DaVinci™ Digital Media Processors Silicon Revisions 3.0, 2.1</p> <p>Silicon Errata</p> <div style="text-align: right; background-color: red; color: white; padding: 10px;">  </div> <p style="text-align: center; font-size: small;">Literature Number: SPRZ343C September 2011 – Revised March 2013</p>			

Revision History

This silicon errata revision history highlights the technical changes made to the SPRZ343A revision to make it an SPRZ343B revision, as well as the technical changes made to the SPRZ343B revision to make it an SPRZ343C revision.

Scope: Applicable updates relating to the TMS320DM814x devices have been incorporated.

DM814x Revision History

SEE	ADDITIONS/MODIFICATIONS/DELETIONS
Revision C (Silicon Revision 3.0) Changes below:	
Global	Added Silicon Revision 3.0 device-specific data
Section 1.2	Package Symbolization and Revision Identification: <ul style="list-style-type: none"> • Updated/Changed "Figure 1 shows ..." paragraph
Figure 1	Example, Device Revision Codes: <ul style="list-style-type: none"> • Updated figure to show an example of silicon revision 3.0 ("C" or "S")
Table 1	TMS320DM814x Device Revision Codes: <ul style="list-style-type: none"> • Added Silicon Revision 3.0 ("C") device-specific data
Section 2	Silicon Revision 3.0 Usage Notes and Known Design Exceptions to Functional Specifications: Added new section
Section 2.1	Usage Notes for Silicon Revision 3.0: Added new section Moved the following 2.1 Usage Notes to this new section: <ul style="list-style-type: none"> • Section 2.1.1, DDR3: JEDEC Compliance for Maximum Self-Refresh Command Limit • Section 2.1.2, Some PLLs Only Support Even M2 Post Dividers • Section 2.1.3, DDR2 and DDR3 Requires Software Leveling
Section 2.2	Silicon Revision 3.0 Known Design Exceptions to Functional Specifications: Added new section Moved all other 2.1 Advisories to this section except for these: <ul style="list-style-type: none"> • Advisory 2.1.27, SATA: Unable to Operate Both SATA and VOUT0 Without SATA Locking Up • Advisory 2.1.28, SATA: Link Establishment Fails With SATA GEN3 Capable Targets • Advisory 2.1.51, HDVPSS: VIP Capture of One-Line Frame to VIP LO Port Immediately After HDVPSS Reset or VIP Client Abort Causes Lockup • Advisory 2.1.59, HDVPSS: Occasionally, Chip Lockup Occurs When HDVPSS VIP is Performing Single-Channel Capture, Sending Tiled Data to DDR and Connect/Disconnect Events are Occurring • Advisory 2.1.88, DDR DMM: Continuous Writes From Cortex-A8 Occasionally Starve Other Requestors for DDR Bandwidth • Advisory 2.1.87, Control Module, Pin Configuration (PINCNTLx), 3.3 V Mode Operation: Reduction in Power-On Hours May Occur if the Input Receiver is Disabled
Section 3.1	Usage Notes for Silicon Revision 2.1: <ul style="list-style-type: none"> • Updated/Changed "Silicon revision 2.1 applicable usage notes ..." paragraph
Section 3.2	Silicon Revision 2.1 Known Design Exceptions to Functional Specifications: <ul style="list-style-type: none"> • Updated/Changed "This is a list of the device revision 2.1 known ..." paragraph • Added Advisory 2.1.59, HDVPSS: Occasionally, Chip Lockup Occurs When HDVPSS VIP is Performing Single-Channel Capture, Sending Tiled Data to DDR and Connect/Disconnect Events are Occurring

DM814x Revision History (continued)

SEE	ADDITIONS/MODIFICATIONS/DELETIONS
Revision B (Silicon Revision 2.1) Changes below:	
Global	Updated/Changed "DEMMU" to "System MMU" Updated/Changed "Digital Media Processors" to "Video Processors"
Section 3.2	<p><i>Silicon Revision 2.1 Known Design Exceptions to Functional Specifications:</i></p> <p>Updated/Changed the Data Manual Doc Titles</p> <p>Advisory 2.1.25, System DEMMU May Hang When Used in Table-Walk Mode:</p> <ul style="list-style-type: none"> Updated/Changed the System MMU Entries (Entry 1 through Entry 7) code in the System MMU Lockdown Example. <p>Added the following Advisories to this section:</p> <ul style="list-style-type: none"> Advisory 2.1.51, HDVPSS: VIP Capture of One-Line Frame to VIP LO Port Immediately After HDVPSS Reset or VIP Client Abort Causes Lockup Advisory 2.1.54, VPDMA Line Limit Feature: Descriptor Reports All Fields as Even, but Captures 30 Even and 30 Odd Fields in Memory Advisory 2.1.55, HPVPSS VIP Inline Color Space Converter (CSC): In Interlaced Embedded or Discrete Sync Mode, Descriptor Reports All Fields as Even, but Captures 30 Even and 30 Odd Fields In Memory Advisory 2.1.58, HDVPSS: HDVPSS VIP Reset Sequence is Occasionally Unsuccessful if VPDMA is Writing Output Descriptors for VIP Captured Data Advisory 2.1.60, HDVPSS: Occasionally, During Connect/Disconnect and When Line or Width Limit Feature Not Used, Any Memory Areas Can Be Overwritten Advisory 2.1.62, HDVPSS: Discrete Sync Interlaced Output Mode: Vertical Sync Output For Odd Fields May Not Correctly Detect Video Signal Advisory 2.1.63, HDVPSS: VIP Single-Channel Capture Using Tiled Output Can Lead To VIP Lockup if Connect/Disconnect Events Occur Advisory 2.1.66, PCI Express (PCIe): PCIe Boot Fails When Connected to Some PCs Advisory 2.1.68, DDR DMM: Continuous Writes From Cortex-A8 Occasionally Starve Other Requestors for DDR Bandwidth Advisory 2.1.70, USB: A USB Device that Responds to a Spurious Invalid Short Packet may Lock up the Bus Advisory 2.1.71, ROMCODE: PCIe Boot is Unstable Advisory 2.1.72, ROMCODE: ROM Code Does Not Support Booting from eMMC Devices of Size 4GB or More Advisory 2.1.76, UART: Extra Assertion of the FIFO Transmit DMA Request, UARTi_DMA_TX Advisory 2.1.79, EDMA: TC0 and TC1 Read Accesses Always Use Physical Address Advisory 2.1.80, Power Sequencing: CVDD versus CVDD_* Advisory 2.1.81, Power Sequencing: 3.3V DVDD* versus VDDA_1P8 Advisory 2.1.82, Power Sequencing: DVDD_DDR[x] versus 3.3V DVDD* Supplies Advisory 2.1.85, EMAC and Switch Subsystem: Reset Isolation Feature is Not Supported Advisory 2.1.87, Control Module, Pin Configuration (PINCNTLx), 3.3 V Mode Operation: Reduction in Power-On Hours May Occur if the Input Receiver is Disabled Advisory 2.1.88, Control Module, Pin Configuration (PINCNTLx): ROM Modifies Bit 19

NOTE: Page numbers for previous revisions may differ from page numbers in the current version.

TI Information – Selective Disclosure

TMS320DM8127 DaVinci™ Digital Media Processors Silicon Revisions 3.0, 2.1

Silicon Errata



Literature Number: SPRZ385B
June 2012–Revised March 2013

Revision History

This silicon errata revision history highlights the technical changes made to the SPRZ385 revision to make it an SPRZ385A revision, as well as the technical changes made to the SPRZ385A revision to make it an SPRZ385B revision.

Scope: Applicable updates relating to the TMS320DM812x devices have been incorporated.

DM812x Revision History

SEE	ADDITIONS/MODIFICATIONS/DELETIONS
Revision B (Silicon Revision 3.0) Changes below:	
Global	Added Silicon Revision 3.0 device-specific data
Section 1.2	Package Symbolization and Revision Identification: <ul style="list-style-type: none"> • Updated/Changed "Figure 1 shows ..." paragraph
Figure 1	Example, Device Revision Codes: <ul style="list-style-type: none"> • Updated figure to show an example of silicon revision 3.0 ("S")
Table 1	TMS320DM8127 Device Revision Codes: <ul style="list-style-type: none"> • Added Silicon Revision 3.0 ("C") device-specific data
Section 2	Silicon Revision 3.0 Usage Notes and Known Design Exceptions to Functional Specifications: Added new section
Section 2.1	Usage Notes for Silicon Revision 3.0: Added new section Moved the following 2.1 Usage Notes to this new section: <ul style="list-style-type: none"> • Section 2.1.1, DDR3: JEDEC Compliance for Maximum Self-Refresh Command Limit • Section 2.1.2, Some PLLs Only Support Even M2 Post Dividers • Section 2.1.3, DDR2 and DDR3 Requires Software Leveling
Section 2.2	Silicon Revision 3.0 Known Design Exceptions to Functional Specifications: Added new section Moved all other 2.1 Advisories to this section except for these: <ul style="list-style-type: none"> • Advisory 2.1.51, HDVPSS: VIP Capture of One-Line Frame to VIP LO Port Immediately After HDVPSS Reset or VIP Client Abort Causes Lockup • Advisory 2.1.59, HDVPSS: Occasionally, Chip Lockup Occurs When HDVPSS VIP is Performing Single-Channel Capture, Sending Tiled Data to DDR and Connect/Disconnect Events are Occurring • Advisory 2.1.68, DDR DMM: Continuous Writes From Cortex-A8 Occasionally Starve Other Requestors for DDR Bandwidth • Advisory 2.1.87, Control Module, Pin Configuration (PINCNTLx), 3.3 V Mode Operation: Reduction in Power-On Hours May Occur if the Input Receiver is Disabled
Section 3.1	Usage Notes for Silicon Revision 2.1: <ul style="list-style-type: none"> • Updated/Changed "Silicon revision 2.1 applicable usage notes ..." paragraph
Section 3.2	Silicon Revision 2.1 Known Design Exceptions to Functional Specifications: <ul style="list-style-type: none"> • Updated/Changed "This is a list of the device revision 2.1 known ..." paragraph • Added Advisory 2.1.59, HDVPSS: Occasionally, Chip Lockup Occurs When HDVPSS VIP is Performing Single-Channel Capture, Sending Tiled Data to DDR and Connect/Disconnect Events are Occurring

DM812x Revision History (continued)

SEE	ADDITIONS/MODIFICATIONS/DELETIONS
Revision A (Silicon Revision 2.1) Changes below:	
Global	Updated/Changed "DEMMU" to "System MMU" Updated/Changed "Digital Media Processors" to "Video Processors"
Section 3.2	<p><i>Silicon Revision 2.1 Known Design Exceptions to Functional Specifications:</i></p> <p>Advisory 2.1.25, System DEMMU May Hang When Used in Table-Walk Mode:</p> <ul style="list-style-type: none"> • Updated/Changed the System MMU Entries (Entry 1 through Entry 7) code in the System MMU Lockdown Example. <p>Added the following Advisories to this section:</p> <ul style="list-style-type: none"> • Advisory 2.1.51, HDVPSS: VIP Capture of One-Line Frame to VIP LO Port Immediately After HDVPSS Reset or VIP Client Abort Causes Lockup • Advisory 2.1.54, VPDMA Line Limit Feature: Descriptor Reports All Fields as Even, but Captures 30 Even and 30 Odd Fields in Memory • Advisory 2.1.55, HPVPSS VIP Inline Color Space Converter (CSC): In Interlaced Embedded or Discrete Sync Mode, Descriptor Reports All Fields as Even, but Captures 30 Even and 30 Odd Fields in Memory • Advisory 2.1.58, HDVPSS: HDVPSS VIP Reset Sequence is Occasionally Unsuccessful if VPDMA is Writing Output Descriptors for VIP Captured Data • Advisory 2.1.60, HDVPSS: Occasionally, During Connect/Disconnect and When Line or Width Limit Feature Not Used, Any Memory Areas Can Be Overwritten • Advisory 2.1.62, HDVPSS: Discrete Sync Interlaced Output Mode: Vertical Sync Output For Odd Fields May Not Correctly Detect Video Signal • Advisory 2.1.63, HDVPSS: VIP Single-Channel Capture Using Tiled Output Can Lead To VIP Lockup if Connect/Disconnect Events Occur • Advisory 2.1.66, PCI Express (PCIe): PCIe Boot Fails When Connected to Some PCs • Advisory 2.1.68, DDR DMM: Continuous Writes From Cortex-A8 Occasionally Starve Other Requestors for DDR Bandwidth • Advisory 2.1.70, USB: A USB Device that Responds to a Spurious Invalid Short Packet may Lock up the Bus • Advisory 2.1.71, ROMCODE: PCIe Boot is Unstable • Advisory 2.1.72, ROMCODE: ROM Code Does Not Support Booting from eMMC Devices of Size 4GB or More • Advisory 2.1.76, UART: Extra Assertion of the FIFO Transmit DMA Request, UARTi_DMA_TX • Advisory 2.1.79, EDMA: TC0 and TC1 Read Accesses Always Use Physical Address • Advisory 2.1.80, Power Sequencing: CVDD versus CVDD_* • Advisory 2.1.81, Power Sequencing: 3.3V DVDD* versus VDDA_1P8 • Advisory 2.1.82, Power Sequencing: DVDD_DDR[x] versus 3.3V DVDD* Supplies • Advisory 2.1.85, EMAC and Switch Subsystem: Reset Isolation Feature is Not Supported • Advisory 2.1.87, Control Module, Pin Configuration (PINCNTLx), 3.3 V Mode Operation: Reduction in Power-On Hours May Occur if the Input Receiver is Disabled • Advisory 2.1.88, Control Module, Pin Configuration (PINCNTLx): ROM Modifies Bit 19

NOTE: Page numbers for previous revisions may differ from page numbers in the current version.

TI Information – Selective Disclosure

DRA64x/DRA65x Automotive Media Applications Processors Silicon Revisions 3.0, 2.1, 1.1, 1.0

Silicon Errata



Literature Number: SPRZ348B
February 2012–Revised March 2013

Revision History

This silicon errata revision history highlights the technical changes made to the SPRZ346 revision to make it an SPRZ346A revision, as well as the technical changes made to the SPRZ346A revision to make it an SPRZ346B revision.

Scope: Applicable updates relating to the DRA64x/DRA65x devices have been incorporated.

DRA64x/DRA65x Revision History

SEE	ADDITIONS/MODIFICATIONS/DELETIONS
Revision B (Silicon Revision 3.0) Changes below:	
Global	Added Silicon Revision 3.0 device-specific data
Section 1.2	Package Symbolization and Revision Identification: <ul style="list-style-type: none"> Updated/Changed "Figure 1 shows ..." paragraph
Figure 1	Example, Device Revision Codes: <ul style="list-style-type: none"> Updated figure to show an example of silicon revision 3.0 ("C")
Table 1	DRA64x/DRA65x Device Revision Codes: <ul style="list-style-type: none"> Added Silicon Revision 3.0 ("C") device-specific data
Section 2	Silicon Revision 3.0 Usage Notes and Known Design Exceptions to Functional Specifications: Added <i>new</i> section
Section 2.1	Usage Notes for Silicon Revision 3.0: Added <i>new</i> section Moved the following 2.1 and earlier Usage Notes to this <i>new</i> section: <ul style="list-style-type: none"> Section 2.1.1, DDR3: JEDEC Compliance for Maximum Self-Refresh Command Limit Section 2.1.2, Some PLLs Only Support Even M2 Post Dividers Section 2.1.3, DDR2 and DDR3 Requires Software Leveling
Section 2.2	Silicon Revision 3.0 Known Design Exceptions to Functional Specifications: Added <i>new</i> section Moved all other 2.1 and earlier Advisories to this section except for these: <ul style="list-style-type: none"> <ul style="list-style-type: none"> Advisory 2.1.27, SATA: Unable to Operate Both SATA and VOUT0 Without SATA Locking Up Advisory 2.1.28, SATA: Link Establishment Fails With SATA GEN3 Capable Targets Advisory 2.1.51, HDVPSS: VIP Capture of One-Line Frame to VIP LO Port Immediately After HDVPSS Reset or VIP Client Abort Causes Lockup Advisory 2.1.59, HDVPSS: Occasionally, Chip Lockup Occurs When HDVPSS VIP is Performing Single-Channel Capture, Sending Tiled Data to DDR and Connect/Disconnect Events are Occurring Advisory 2.1.68, DDR DMM: Continuous Writes From Cortex-A8 Occasionally Starve Other Requestors for DDR Bandwidth Advisory 2.1.87, Control Module, Pin Configuration (PINCNTLx), 3.3 V Mode Operation: Reduction in Power-On Hours May Occur if the Input Receiver is Disabled
Section 3.1	Usage Notes for Silicon Revision 2.1: <ul style="list-style-type: none"> Updated/Changed "Silicon revision 2.1 applicable usage notes ..." paragraph
Section 3.2	Silicon Revision 2.1 Known Design Exceptions to Functional Specifications: <ul style="list-style-type: none"> Updated/Changed "This is a list of the device revision 2.1 known ..." paragraph Added <i>Advisory 2.1.59</i>, HDVPSS: Occasionally, Chip Lockup Occurs When HDVPSS VIP is Performing Single-Channel Capture, Sending Tiled Data to DDR and Connect/Disconnect Events are Occurring

DRA64x/DRA65x Revision History (continued)

SEE	ADDITIONS/MODIFICATIONS/DELETIONS
Revision A (Silicon Revision 2.1) Changes below:	
Global	Updated/Changed "DEMMU" to "System MMU" Updated/Changed "Digital Media Processors" to "Video Processors"
Section 3.2	<p><i>Silicon Revision 2.1 Known Design Exceptions to Functional Specifications:</i></p> <p>Updated/Changed the Data Manual Doc Titles</p> <p>Advisory 2.1.25, System DEMMU May Hang When Used in Table-Walk Mode:</p> <ul style="list-style-type: none"> • Updated/Changed the System MMU Entries (Entry 1 through Entry 7) code in the System MMU Lockdown Example. <p>Added the following Advisories to this section:</p> <ul style="list-style-type: none"> • Advisory 2.1.51, HDVPSS: VIP Capture of One-Line Frame to VIP LO Port Immediately After HDVPSS Reset or VIP Client Abort Causes Lockup • Advisory 2.1.54, VPDMA Line Limit Feature: Descriptor Reports All Fields as Even, but Captures 30 Even and 30 Odd Fields in Memory • Advisory 2.1.55, HPVPSS VIP Inline Color Space Converter (CSC): In Interlaced Embedded or Discrete Sync Mode, Descriptor Reports All Fields as Even, but Captures 30 Even and 30 Odd Fields in Memory • Advisory 2.1.58, HDVPSS: HDVPSS VIP Reset Sequence is Occasionally Unsuccessful if VPDMA is Writing Output Descriptors for VIP Captured Data • Advisory 2.1.60, HDVPSS: Occasionally, During Connect/Disconnect and When Line or Width Limit Feature Not Used, Any Memory Areas Can Be Overwritten • Advisory 2.1.62, HDVPSS: Discrete Sync Interlaced Output Mode: Vertical Sync Output For Odd Fields May Not Correctly Detect Video Signal • Advisory 2.1.63, HDVPSS: VIP Single-Channel Capture Using Tiled Output Can Lead To VIP Lockup if Connect/Disconnect Events Occur • Advisory 2.1.66, PCI Express (PCIe): PCIe Boot Fails When Connected to Some PCs • Advisory 2.1.68, DDR DMM: Continuous Writes From Cortex-A8 Occasionally Starve Other Requestors for DDR Bandwidth • Advisory 2.1.70, USB: A USB Device that Responds to a Spurious Invalid Short Packet may Lock up the Bus • Advisory 2.1.71, ROMCODE: PCIe Boot is Unstable • Advisory 2.1.72, ROMCODE: ROM Code Does Not Support Booting from eMMC Devices of Size 4GB or More • Advisory 2.1.76, UART: Extra Assertion of the FIFO Transmit DMA Request, UARTi_DMA_TX • Advisory 2.1.79, EDMA: TC0 and TC1 Read Accesses Always Use Physical Address • Advisory 2.1.80, Power Sequencing: CVDD versus CVDD_* • Advisory 2.1.81, Power Sequencing: 3.3V DVDD* versus VDDA_1P8 • Advisory 2.1.82, Power Sequencing: DVDD_DDR[x] versus 3.3V DVDD* Supplies • Advisory 2.1.84, MLB: Potential for Misaligned Data in Multi-Frame per Sub-buffer Mode • Advisory 2.1.85, EMAC and Switch Subsystem: Reset Isolation Feature is Not Supported • Advisory 2.1.87, Control Module, Pin Configuration (PINCNTLx), 3.3 V Mode Operation: Reduction in Power-On Hours May Occur if the Input Receiver is Disabled • Advisory 2.1.88, Control Module, Pin Configuration (PINCNTLx): ROM Modifies Bit 19

NOTE: Page numbers for previous revisions may differ from page numbers in the current version.

**AM387x Sitara™
ARM® Microprocessors (MPUs)
Silicon Revisions 3.0, 2.1**

Silicon Errata



Literature Number: SPRZ345C
September 2011–Revised March 2013

Revision History

This silicon errata revision history highlights the technical changes made to the SPRZ345A revision to make it an SPRZ345B revision, as well as the technical changes made to the SPRZ345B revision to make it an SPRZ345C revision.

Scope: Applicable updates relating to the AM387x devices have been incorporated.

AM387x Revision History

SEE	ADDITIONS/MODIFICATIONS/DELETIONS
Revision C (Silicon Revision 3.0) Changes below:	
Global	Added Silicon Revision 3.0 device-specific data
Section 1.2	Package Symbolization and Revision Identification: <ul style="list-style-type: none"> Updated/Changed "Figure 1 shows ..." paragraph
Figure 1	Example, Device Revision Codes: <ul style="list-style-type: none"> Updated figure to show an example of silicon revision 3.0 ("C")
Table 1	AM387x Device Revision Codes: <ul style="list-style-type: none"> Added Silicon Revision 3.0 ("C") device-specific data
Section 2	Silicon Revision 3.0 Usage Notes and Known Design Exceptions to Functional Specifications: Added <i>new</i> section
Section 2.1	Usage Notes for Silicon Revision 3.0: Added <i>new</i> section Moved the following 2.1 Usage Notes to this <i>new</i> section: <ul style="list-style-type: none"> Section 2.1.1, DDR3: JEDEC Compliance for Maximum Self-Refresh Command Limit Section 2.1.2, Some PLLs Only Support Even M2 Post Dividers Section 2.1.3, DDR2 and DDR3 Requires Software Leveling
Section 2.2	Silicon Revision 3.0 Known Design Exceptions to Functional Specifications: Added <i>new</i> section Moved all other 2.1 Advisories to this section except for these: <ul style="list-style-type: none"> Advisory 2.1.27, SATA: Unable to Operate Both SATA and VOUT0 Without SATA Locking Up Advisory 2.1.28, SATA: Link Establishment Fails With SATA GEN3 Capable Targets Advisory 2.1.51, HDVPSS: VIP Capture of One-Line Frame to VIP LO Port Immediately After HDVPSS Reset or VIP Client Abort Causes Lockup Advisory 2.1.59, HDVPSS: Occasionally, Chip Lockup Occurs When HDVPSS VIP is Performing Single-Channel Capture, Sending Tiled Data to DDR and Connect/Disconnect Events are Occurring Advisory 2.1.68, DDR DMM: Continuous Writes From Cortex-A8 Occasionally Starve Other Requestors for DDR Bandwidth Advisory 2.1.87, Control Module, Pin Configuration (PINCNTLx), 3.3 V Mode Operation: Reduction in Power-On Hours May Occur if the Input Receiver is Disabled
Section 3.1	Usage Notes for Silicon Revision 2.1: <ul style="list-style-type: none"> Updated/Changed "Silicon revision 2.1 applicable usage notes ..." paragraph
Section 3.2	Silicon Revision 2.1 Known Design Exceptions to Functional Specifications: <ul style="list-style-type: none"> Updated/Changed "This is a list of the device revision 2.1 known ..." paragraph Added Advisory 2.1.59, HDVPSS: Occasionally, Chip Lockup Occurs When HDVPSS VIP is Performing Single-Channel Capture, Sending Tiled Data to DDR and Connect/Disconnect Events are Occurring

AM387x Revision History (continued)

SEE	ADDITIONS/MODIFICATIONS/DELETIONS
Revision B (Silicon)	Revision 2.1) Changes below:
Global	Updated/Changed "Digital Media Processors" to "Video Processors"
Section 3.2	<p><i>Silicon Revision 2.1 Known Design Exceptions to Functional Specifications:</i></p> <p>Updated/Changed the Data Manual Doc Titles</p> <p>Added the following Advisories to this section:</p> <ul style="list-style-type: none"> • Advisory 2.1.51, HDVPSS: VIP Capture of One-Line Frame to VIP LO Port Immediately After HDVPSS Reset or VIP Client Abort Causes Lockup • Advisory 2.1.54, VPDMA Line Limit Feature: Descriptor Reports All Fields as Even, but Captures 30 Even and 30 Odd Fields in Memory • Advisory 2.1.55, HPVPSS VIP Inline Color Space Converter (CSC): In Interlaced Embedded or Discrete Sync Mode, Descriptor Reports All Fields as Even, but Captures 30 Even and 30 Odd Fields in Memory • Advisory 2.1.58, HDVPSS: HDVPSS VIP Reset Sequence is Occasionally Unsuccessful if VPDMA is Writing Output Descriptors for VIP Captured Data • Advisory 2.1.60, HDVPSS: Occasionally, During Connect/Disconnect and When Line or Width Limit Feature Not Used, Any Memory Areas Can Be Overwritten • Advisory 2.1.62, HDVPSS: Discrete Sync Interlaced Output Mode: Vertical Sync Output For Odd Fields May Not Correctly Detect Video Signal • Advisory 2.1.63, HDVPSS: VIP Single-Channel Capture Using Tiled Output Can Lead To VIP Lockup if Connect/Disconnect Events Occur • Advisory 2.1.66, PCI Express (PCIe): PCIe Boot Fails When Connected to Some PCs • Advisory 2.1.68, DDR DMM: Continuous Writes From Cortex-A8 Occasionally Starve Other Requestors for DDR Bandwidth • Advisory 2.1.70, USB: A USB Device that Responds to a Spurious Invalid Short Packet may Lock up the Bus • Advisory 2.1.71, ROMCODE: PCIe Boot is Unstable • Advisory 2.1.72, ROMCODE: ROM Code Does Not Support Booting from eMMC Devices of Size 4GB or More • Advisory 2.1.76, UART: Extra Assertion of the FIFO Transmit DMA Request, UARTi_DMA_TX • Advisory 2.1.79, EDMA: TC0 and TC1 Read Accesses Always Use Physical Address • Advisory 2.1.80, Power Sequencing: CVDD versus CVDD_ARM • Advisory 2.1.81, Power Sequencing: 3.3V DVDD* versus VDDA_1P8 • Advisory 2.1.82, Power Sequencing: DVDD_DDR[x] versus 3.3V DVDD* Supplies • Advisory 2.1.85, EMAC and Switch Subsystem: Reset Isolation Feature is Not Supported • Advisory 2.1.87, Control Module, Pin Configuration (PINCNTLx), 3.3 V Mode Operation: Reduction in Power-On Hours May Occur if the Input Receiver is Disabled • Advisory 2.1.88, Control Module, Pin Configuration (PINCNTLx): ROM Modifies Bit 19

NOTE: Page numbers for previous revisions may differ from page numbers in the current version.

TI Information – Selective Disclosure

TMS320DM814x DaVinci™ Digital Media Processors — Secure Silicon Revisions 3.0, 2.1

Silicon Errata



Literature Number: SPRZ361C
September 2011—Revised March 2013

Revision History

This silicon errata revision history highlights the technical changes made to the SPRZ361A revision to make it an SPRZ361B revision, as well as the technical changes made to the SPRZ361B revision to make it an SPRZ361C revision.

Scope: Applicable updates relating to the TMS320DM814x devices have been incorporated.

DM814x Revision History

SEE	ADDITIONS/MODIFICATIONS/DELETIONS
Revision C (Silicon Revision 3.0) Changes below:	
Global	Added Silicon Revision 3.0 device-specific data
Section 1.2	Package Symbolization and Revision Identification: <ul style="list-style-type: none"> • Updated/Changed "Figure 1 shows ..." paragraph
Figure 1	Example, Device Revision Codes: <ul style="list-style-type: none"> • Updated figure to show an example of silicon revision 3.0 ("C" or "S")
Table 1	TMS320DM814x Device Revision Codes: <ul style="list-style-type: none"> • Added Silicon Revision 3.0 ("C") device-specific data
Section 2	Silicon Revision 3.0 Usage Notes and Known Design Exceptions to Functional Specifications: Added <i>new</i> section
Section 2.1	Usage Notes for Silicon Revision 3.0: Added <i>new</i> section Moved the following 2.1 Usage Notes to this <i>new</i> section: <ul style="list-style-type: none"> • Section 2.1.1, DDR3: JEDEC Compliance for Maximum Self-Refresh Command Limit • Section 2.1.2, Some PLLs Only Support Even M2 Post Dividers • Section 2.1.3, DDR2 and DDR3 Requires Software Leveling
Section 2.2	Silicon Revision 3.0 Known Design Exceptions to Functional Specifications: Added <i>new</i> section Moved all other 2.1 Advisories to this section except for these: <ul style="list-style-type: none"> • • Advisory 2.1.27, SATA: Unable to Operate Both SATA and VOUT0 Without SATA Locking Up • Advisory 2.1.28, SATA: Link Establishment Fails With SATA GEN3 Capable Targets • Advisory 2.1.51, HDVPSS: VIP Capture of One-Line Frame to VIP LO Port Immediately After HDVPSS Reset or VIP Client Abort Causes Lockup • Advisory 2.1.59, HDVPSS: Occasionally, Chip Lockup Occurs When HDVPSS VIP is Performing Single-Channel Capture, Sending Tiled Data to DDR and Connect/Disconnect Events are Occurring • Advisory 2.1.88, DDR DMM: Continuous Writes From Cortex-A8 Occasionally Starve Other Requestors for DDR Bandwidth • Advisory 2.1.87, Control Module, Pin Configuration (PINCNTLx), 3.3 V Mode Operation: Reduction in Power-On Hours May Occur if the Input Receiver is Disabled
Section 3.1	Usage Notes for Silicon Revision 2.1: <ul style="list-style-type: none"> • Updated/Changed "Silicon revision 2.1 applicable usage notes ..." paragraph
Section 3.2	Silicon Revision 2.1 Known Design Exceptions to Functional Specifications: <ul style="list-style-type: none"> • Updated/Changed "This is a list of the device revision 2.1 known ..." paragraph • Added Advisory 2.1.59, HDVPSS: Occasionally, Chip Lockup Occurs When HDVPSS VIP is Performing Single-Channel Capture, Sending Tiled Data to DDR and Connect/Disconnect Events are Occurring

DM814x Revision History (continued)

SEE	ADDITIONS/MODIFICATIONS/DELETIONS
Revision B (Silicon Revision 2.1) Changes below:	
Global	Updated/Changed "DEMMU" to "System MMU" Updated/Changed "Digital Media Processors" to "Video Processors"
Section 3.2	<p><i>Silicon Revision 2.1 Known Design Exceptions to Functional Specifications:</i></p> <p>Updated/Changed the Data Manual Doc Titles</p> <p>Advisory 2.1.25, System DEMMU May Hang When Used in Table-Walk Mode:</p> <ul style="list-style-type: none"> Updated/Changed the System MMU Entries (Entry 1 through Entry 7) code in the System MMU Lockdown Example. <p>Added the following Advisories to this section:</p> <ul style="list-style-type: none"> Advisory 2.1.51, HDVPSS: VIP Capture of One-Line Frame to VIP LO Port Immediately After HDVPSS Reset or VIP Client Abort Causes Lockup Advisory 2.1.54, VPDMA Line Limit Feature: Descriptor Reports All Fields as Even, but Captures 30 Even and 30 Odd Fields in Memory Advisory 2.1.55, HPVPSS VIP Inline Color Space Converter (CSC): In Interlaced Embedded or Discrete Sync Mode, Descriptor Reports All Fields as Even, but Captures 30 Even and 30 Odd Fields In Memory Advisory 2.1.58, HDVPSS: HDVPSS VIP Reset Sequence is Occasionally Unsuccessful if VPDMA is Writing Output Descriptors for VIP Captured Data Advisory 2.1.60, HDVPSS: Occasionally, During Connect/Disconnect and When Line or Width Limit Feature Not Used, Any Memory Areas Can Be Overwritten Advisory 2.1.62, HDVPSS: Discrete Sync Interlaced Output Mode: Vertical Sync Output For Odd Fields May Not Correctly Detect Video Signal Advisory 2.1.63, HDVPSS: VIP Single-Channel Capture Using Tiled Output Can Lead To VIP Lockup if Connect/Disconnect Events Occur Advisory 2.1.66, PCI Express (PCIe): PCIe Boot Fails When Connected to Some PCs Advisory 2.1.68, DDR DMM: Continuous Writes From Cortex-A8 Occasionally Starve Other Requestors for DDR Bandwidth Advisory 2.1.70, USB: A USB Device that Responds to a Spurious Invalid Short Packet may Lock up the Bus Advisory 2.1.71, ROMCODE: PCIe Boot is Unstable Advisory 2.1.72, ROMCODE: ROM Code Does Not Support Booting from eMMC Devices of Size 4GB or More Advisory 2.1.76, UART: Extra Assertion of the FIFO Transmit DMA Request, UARTi_DMA_TX Advisory 2.1.79, EDMA: TC0 and TC1 Read Accesses Always Use Physical Address Advisory 2.1.80, Power Sequencing: CVDD versus CVDD_* Advisory 2.1.81, Power Sequencing: 3.3V DVDD* versus VDDA_1P8 Advisory 2.1.82, Power Sequencing: DVDD_DDR[x] versus 3.3V DVDD* Supplies Advisory 2.1.85, EMAC and Switch Subsystem: Reset Isolation Feature is Not Supported Advisory 2.1.87, Control Module, Pin Configuration (PINCNTLx), 3.3 V Mode Operation: Reduction in Power-On Hours May Occur if the Input Receiver is Disabled Advisory 2.1.88, Control Module, Pin Configuration (PINCNTLx): ROM Modifies Bit 19

NOTE: Page numbers for previous revisions may differ from page numbers in the current version.

The datasheet number will be changing.

Device Family	Change From:	Change To:
DM814x	SPRZ343A	SPRZ343C
DM812x	SPRZ385	SPRZ385B
DRA64x/DRA65x	SPRZ346	SPRZ346B
AM387x	SPRZ345A	SPRZ345C
DM814xSEC	SPRZ361A	SPRZ361C

Reason for Change:			
To more accurately reflect device characteristics			
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):			
Electrical specification performance changes as indicated above.			
Changes to product identification resulting from this PCN:			
None			
Product Affected:			
AM3871CCYE100	DRA655AVWBICYERQ1	TMS320DM8148CCYE0	TMX320DM8148CYE
AM3871CCYE80	DRA657CICYERQ1	TMS320DM8148CCYE1	TMX320DRA6XXCYE
AM3874BCYE100	TDA1MEDBCYEQ7Q1	TMS320DM8148CCYE2	XAM3874BCYE
AM3874BCYE80	TDA1MSACCYEQ4Q1	TMS320DM8148CCYE2F	XDRA62XAZKK
AM3874CCYE100	TDA1MSVBCYEQ5Q1	TMS320DM8148CCYEA0	XDRA62XHSZKK
AM3874CCYE80	TMS320DM8127BCYE3	TMS320DM8148SCYE0	XDRA65XBCYEP
AM3874CCYEA80	TMS320DM8127BCYED3	TMS320DM8148SCYE1	XDRA6XXBCYE
DM8148CR2CYE2	TMS320DM8147BCYE0	TMS320DM8148SCYE2	XDRA6XXBCYEF
DRA631AIZKKQ1	TMS320DM8147BCYE1	TMS320DM8148SCYEA0	XDRA6XXCCYE
DRA633AIZKKQ1	TMS320DM8147BCYE2	TMX320C6A8148BCYE	XTDA1MEVAASQX
DRA643CICYEQ1	TMS320DM8147SCYE1	TMX320DM8147BCYE0	XTDA1MEVCYEQX
DRA644BICYEQ1	TMS320DM8147SCYE2	TMX320DM8147BCYE1	XTDA1MXXBCYEQX
DRA646BICYEQ1	TMS320DM8148BCYE0	TMX320DM8147BCYE2	XTDA1MXXCCYEQX
DRA647CICYEQ1	TMS320DM8148BCYE1	TMX320DM8148BCYE	
DRA648CICYEQ1	TMS320DM8148BCYE2	TMX320DM8148CCYE2	

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com