



## Product Change Notification / SYST-13FXEP904

---

### Date:

14-Jul-2022

### Product Category:

Ethernet Switches

### PCN Type:

Document Change

### Notification Subject:

Data Sheet - KSZ8775CLX Integrated 5-Port 10/100 Managed Ethernet Switch with Port 4 RMII and Port 5 RGMII/MII/RMII Interfaces - Data Sheet Document Revision

### Affected CPNs:

[SYST-13FXEP904\\_Affected\\_CPN\\_07142022.pdf](#)

[SYST-13FXEP904\\_Affected\\_CPN\\_07142022.csv](#)

### Notification Text:

SYST-13FXEP904

Microchip has released a new Datasheet for the KSZ8775CLX Integrated 5-Port 10/100 Managed Ethernet Switch with Port 4 RMII and Port 5 RGMII/MII/RMII Interfaces - Data Sheet of devices. If you are using one of these devices please read the document located at [KSZ8775CLX Integrated 5-Port 10/100 Managed Ethernet Switch with Port 4 RMII and Port 5 RGMII/MII/RMII Interfaces - Data Sheet](#).

**Notification Status:** Final

#### Description of Change:

Table 4-4 Updated register 23 definition: "Port 3 Control 7" to "Port 1 Control 7". Updated register 39 definition: "Port 3 Control 7" to "Port 2 Control 7".

Table 4-11 Corrected Dynamic MAC Address table headers.

Table 2-1 Updated SCL\_MDC pin definition: max frequency from "50MHz" to "25MHz".

Table 4-4 Updated registers 18, 34, 50, 66, 82, bit 0 definition: "Learning Enable" to "Learning Disable."

Table 4-4 Updated register 76, bit 7 note from: "This bit shouldn't be used for Port 4 SW4-RMII" to "This bit is don't care for Port 4 SW 4-RMII".

Table 4-4 Updated register 77 title from "Port 4 Control 10" to "Reserved".

Table 4-3 Updated register 12 definitions for bits 5 and 4.

**Impacts to Data Sheet:** See above details

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 14 Jul 2022

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

## Attachments:

[KSZ8775CLX Integrated 5-Port 10/100 Managed Ethernet Switch with Port 4 RGMII and Port 5 RGMII/MII/RMII Interfaces - Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

## Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

KSZ8775CLXCC

KSZ8775CLXIC