



# Product Change Notification

## TE Connectivity

Product Change Notification: E-20-004888

PCN Date: 03-APR-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**  
DEUTSCH DT/DTM Swing Tools Molding and Assembly Manufacturing Location Change.

**Description of Changes**  
The Industrial and Commercial Transportation business unit of TE Connectivity is swing transferring the molding on component(s) of the following part number(s) from TE-Empalme, Mexico to TE-Hemet, USA. These PNs are TE proprietary designs, therefore considered catalog/general market product. TE reserves the right to move tool back to prior location/supplier based on business need. Level 4 PPAP (PSW only) will be available upon request via ict-ppap-request@te.com or ePPAP system

**Reason for Changes:**  
This change is necessary to maintain production of these components for our customers due to a forced temporary plant closure as a result of COVID-19. The change will not impact connector performance. IMPORTANT: The current and previous revisions of these parts can be used interchangeably in the field. The change(s) are being phased in gradually and previous revision can remain stocked until use. Shipments of both configurations may be mixed.

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	03-APR-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	03-NOV-2024

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">DT04-3P-EP10</a>	NO						
<a href="#">DT04-3P-P006</a>	NO						
<a href="#">DT06-3S-EP10</a>	NO						
<a href="#">DT06-3S-P006</a>	NO			"6-1899776-0"			
<a href="#">DTM04-12PA</a>	NO			"ZPF00000000130567", "DTM04-12PA-LS", "DTM04-12PA-L"			
<a href="#">DTM04-2P</a>	NO			"ZPF00000000130131", "DTM04-2P-AS", "DTM04-2P-LS", "DTM04-2P-L"			
<a href="#">DTM04-3P</a>	NO			"ZPF00000000130198", "DTM04-3P-LD", "DTM04-3P-LS", "DTM04-3P-L"			
<a href="#">DTM04-4P</a>	NO			"ZPF00000000130263", "DTM04-4P-LS", "DTM04-4P-L", "8202609556", "MSE04832"			
<a href="#">DTM04-6P</a>	NO			"ZPF00000000130335", "DTM04-6P-LD", "DTM04-6P-LS", "DTM04-6P-L"			
<a href="#">DTM06-12SA</a>	NO			"ZPF00000000130575", "DTM06-12SA-LS", "DTM06-12SA-SC", "DTM06-12SA-E", "DTM06-12SA-L", "DTM06-12SA-S"			
<a href="#">DTM06-2S</a>	NO			"ZPF00000000130139", "DTM06-2S-LS", "DTM06-2S-L", "8202609944"			
<a href="#">DTM06-3S</a>	NO			"ZPF00000000130202", "DTM06-3S-LS", "DTM06-3S-L", "8202609699", "8202612555"			
<a href="#">DTM06-4S</a>	NO			"ZPF00000000130267", "820260979"			
<a href="#">DTM06-6S</a>	NO			"ZPF00000000130339", "DTM06-6S-LD", "DTM06-6S-LS", "2231456-1", "2231458-1", "DTM06-6S-E", "DTM06-6S-L"			
<a href="#">WM-12P</a>	NO			"ZPF00000000131479", "WM-12P-MS", "WM-12P-M"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">WM-6P</a>	NO			"ZPF000000000131475"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">DT04-3P-EP10</a>	NO						
<a href="#">DT04-3P-P006</a>	NO						
<a href="#">DT06-3S-EP10</a>	NO						
<a href="#">DT06-3S-P006</a>	NO			"6-1899776-0"			
<a href="#">DTM04-12PA</a>	NO			"ZPF000000000130567", "DTM04-12PA-LS", "DTM04-12PA-L"			
<a href="#">DTM04-2P</a>	NO			"ZPF000000000130131", "DTM04-2P-AS", "DTM04-2P-LS", "DTM04-2P-L"			
<a href="#">DTM04-3P</a>	NO			"ZPF000000000130198", "DTM04-3P-LD", "DTM04-3P-LS", "DTM04-3P-L"			
<a href="#">DTM04-4P</a>	NO			"ZPF000000000130263", "DTM04-4P-LS", "DTM04-4P-L", "8202609556", "MSE04832"			
<a href="#">DTM04-6P</a>	NO			"ZPF000000000130335", "DTM04-6P-LD", "DTM04-6P-LS", "DTM04-6P-L"			
<a href="#">DTM06-12SA</a>	NO			"ZPF000000000130575", "DTM06-12SA-LS", "DTM06-12SA-SC", "DTM06-12SA-E", "DTM06-12SA-L", "DTM06-12SA-S"			
<a href="#">DTM06-2S</a>	NO			"ZPF000000000130139", "DTM06-2S-LS", "DTM06-2S-L", "8202609944"			
<a href="#">DTM06-3S</a>	NO			"ZPF000000000130202", "DTM06-3S-LS", "DTM06-3S-L", "8202609699", "8202612555"			
<a href="#">DTM06-4S</a>	NO			"ZPF000000000130267", "8202606979"			
<a href="#">DTM06-6S</a>	NO			"ZPF000000000130339", "DTM06-6S-LD", "DTM06-6S-LS", "2231456-1", "2231458-1", "DTM06-6S-E", "DTM06-6S-L"			
<a href="#">WM-12P</a>	NO			"ZPF000000000131479", "WM-12P-MS", "WM-12P-M"			
<a href="#">WM-6P</a>	NO			"ZPF000000000131475"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">DT04-3P-EP10</a>	NO						
<a href="#">DT04-3P-P006</a>	NO						
<a href="#">DT06-3S-EP10</a>	NO						
<a href="#">DT06-3S-P006</a>	NO			"6-1899776-0"			
<a href="#">DTM04-12PA</a>	NO			"ZPF000000000130567", "DTM04-12PA-LS", "DTM04-12PA-L"			
<a href="#">DTM04-2P</a>	NO			"ZPF000000000130131", "DTM04-2P-AS", "DTM04-2P-LS", "DTM04-2P-L"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">DTM04-3P</a>	NO			"ZPF000000000130198", "DTM04-3P-LD", "DTM04-3P-LS", "DTM04-3P-L"			
<a href="#">DTM04-4P</a>	NO			"ZPF000000000130263", "DTM04-4P-LS", "DTM04-4P-L", "8202609556", "MSE04832"			
<a href="#">DTM04-6P</a>	NO			"ZPF000000000130335", "DTM04-6P-LD", "DTM04-6P-LS", "DTM04-6P-L"			
<a href="#">DTM06-12SA</a>	NO			"ZPF000000000130575", "DTM06-12SA-LS", "DTM06-12SA-SC", "DTM06-12SA-E", "DTM06-12SA-L", "DTM06-12SA-S"			
<a href="#">DTM06-2S</a>	NO			"ZPF000000000130139", "DTM06-2S-LS", "DTM06-2S-L", "8202609944"			
<a href="#">DTM06-3S</a>	NO			"ZPF000000000130202", "DTM06-3S-LS", "DTM06-3S-L", "8202609699", "8202612555"			
<a href="#">DTM06-4S</a>	NO			"ZPF000000000130267", "8202606979"			
<a href="#">DTM06-6S</a>	NO			"ZPF000000000130339", "DTM06-6S-LD", "DTM06-6S-LS", "2231456-1", "2231458-1", "DTM06-6S-E", "DTM06-6S-L"			
<a href="#">WM-12P</a>	NO			"ZPF000000000131479", "WM-12P-MS", "WM-12P-M"			
<a href="#">WM-6P</a>	NO			"ZPF000000000131475"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">DT04-3P-EP10</a>	NO						
<a href="#">DT04-3P-P006</a>	NO						
<a href="#">DT06-3S-EP10</a>	NO						
<a href="#">DT06-3S-P006</a>	NO			"6-1899776-0"			
<a href="#">DTM04-12PA</a>	NO			"ZPF000000000130567", "DTM04-12PA-LS", "DTM04-12PA-L"			
<a href="#">DTM04-2P</a>	NO			"ZPF000000000130131", "DTM04-2P-AS", "DTM04-2P-LS", "DTM04-2P-L"			
<a href="#">DTM04-3P</a>	NO			"ZPF000000000130198", "DTM04-3P-LD", "DTM04-3P-LS", "DTM04-3P-L"			
<a href="#">DTM04-4P</a>	NO			"ZPF000000000130263", "DTM04-4P-LS", "DTM04-4P-L", "8202609556", "MSE04832"			
<a href="#">DTM04-6P</a>	NO			"ZPF000000000130335", "DTM04-6P-LD", "DTM04-6P-LS", "DTM04-6P-L"			
<a href="#">DTM06-12SA</a>	NO			"ZPF000000000130575", "DTM06-12SA-LS", "DTM06-12SA-SC", "DTM06-12SA-E", "DTM06-12SA-L", "DTM06-12SA-S"			
<a href="#">DTM06-2S</a>	NO			"ZPF000000000130139", "DTM06-2S-LS", "DTM06-2S-L", "8202609944"			
<a href="#">DTM06-3S</a>	NO			"ZPF000000000130202", "DTM06-3S-LS", "DTM06-3S-L", "8202609699", "8202612555"			
<a href="#">DTM06-4S</a>	NO			"ZPF000000000130267", "8202606979"			
<a href="#">DTM06-6S</a>	NO			"ZPF000000000130339", "DTM06-6S-LD", "DTM06-6S-LS", "2231456-1", "2231458-1", "DTM06-6S-E", "DTM06-6S-L"			
<a href="#">WM-12P</a>	NO			"ZPF000000000131479", "WM-12P-MS", "WM-12P-M"			
<a href="#">WM-6P</a>	NO			"ZPF000000000131475"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">DT04-3P-EP10</a>	NO						
<a href="#">DT04-3P-P006</a>	NO						
<a href="#">DT06-3S-EP10</a>	NO						
<a href="#">DT06-3S-P006</a>	NO			"6-1899776-0"			
<a href="#">DTM04-12PA</a>	NO			"ZPF000000000130567", "DTM04-12PA-LS", "DTM04-12PA-L"			
<a href="#">DTM04-2P</a>	NO			"ZPF000000000130131", "DTM04-2P-AS", "DTM04-2P-LS", "DTM04-2P-L"			
<a href="#">DTM04-3P</a>	NO			"ZPF000000000130198", "DTM04-3P-LD", "DTM04-3P-LS", "DTM04-3P-L"			
<a href="#">DTM04-4P</a>	NO			"ZPF000000000130263", "DTM04-4P-LS", "DTM04-4P-L", "8202609556", "MSE04832"			
<a href="#">DTM04-6P</a>	NO			"ZPF000000000130335", "DTM04-6P-LD", "DTM04-6P-LS", "DTM04-6P-L"			
<a href="#">DTM06-12SA</a>	NO			"ZPF000000000130575", "DTM06-12SA-LS", "DTM06-12SA-SC", "DTM06-12SA-E", "DTM06-12SA-L", "DTM06-12SA-S"			
<a href="#">DTM06-2S</a>	NO			"ZPF000000000130139", "DTM06-2S-LS", "DTM06-2S-L", "8202609944"			
<a href="#">DTM06-3S</a>	NO			"ZPF000000000130202", "DTM06-3S-LS", "DTM06-3S-L", "8202609699", "8202612555"			
<a href="#">DTM06-4S</a>	NO			"ZPF000000000130267", "8202606979"			
<a href="#">DTM06-6S</a>	NO			"ZPF000000000130339", "DTM06-6S-LD", "DTM06-6S-LS", "2231456-1", "2231458-1", "DTM06-6S-E", "DTM06-6S-L"			
<a href="#">WM-12P</a>	NO			"ZPF000000000131479", "WM-12P-MS", "WM-12P-M"			
<a href="#">WM-6P</a>	NO			"ZPF000000000131475"			