

<b>Title of Change:</b>	ASPM27 Marking updating
<b>Effective date:</b>	20 Dec 2021
<b>Contact information:</b>	Contact your local onsemi Sales Office or <a href="mailto:Peter.Lee@onsemi.com">Peter.Lee@onsemi.com</a>
<b>Type of notification:</b>	This Product Bulletin is for notification purposes only. onsemi will proceed with implementation of this change upon publication of this Product Bulletin.
<b>Change Category:</b>	added version & current rate in marking section due to customer requesting.
<b>Change Sub-Category(s):</b>	Datasheet/Product Doc change

**Sites Affected:**


<b>onsemi Sites</b>	<b>External Foundry/Subcon Sites</b>
None	None

**Description and Purpose:**

To differentiate between the various versions of ASPM27 products, a top marking change will be implemented. The top marking change will not impact form, fit or function of product(s).

PKG, Ver	OPNs	New marking spec	Meaning
ASPM27-V2	NFVA33065L32	23	Version 2, Current: 30A
ASPM27-V3	NFVA33065L42	33	Version 3, Current: 30A
ASPM27-V2	NFVA35065L32	25	Version 2, Current: 50A
ASPM27-V3	NFVA36065L42	36	Version 3, Current: 60A
ASPM27-V2	NFVA34065L32	24	Version 2, Current: 40A
ASPM27-V3	NFVA35065L42	35	Version 3, Current: 50A
ASPM27-V2	NFVA33065L32-Z007	23	Version 2, Current: 30A
ASPM27-V2	NFVA35065L32-Z007	25	Version 2, Current: 50A

**MARKING DIAGRAM**



- ON = ON Semiconductor Logo
- XX = Version, Current Rate
- XXXXXXXXXXXX = Specific Device Code
- XXX = Lot Number
- Y = Year
- WW = Work Week
- 0000001 = Serial Number

**List of Affected Standard Parts:**

**Note:** Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the **PCN Customized Portal**.

NFVA35065L42	NFVA34065L32	NFVA36065L42
NFVA35065L32	NFVA33065L42	NFVA33065L32

---

**Appendix A: Changed Products**

**PCN#: PB24442Z**  
**Issue Date: Dec 20, 2021**

---

---

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
NFVA35065L32		NA		
NFVA33065L32		NA		